


Certificate of Testing

**CHAIN & RIGGING SUPPLIES LTD**  
136 Captain Springs Rd, Onehunga  
P O Box 13 312, Onehunga, Auckland, N.Z.  
Ph: 09 636 4775 Fax: 09 636 7543  
158 TONNE COMPUTERISED TESTING EQUIPMENT


<b>Customer:</b> TREE TOOLS	<b>Test Number:</b> 17597
<b>Serial No.:</b> #1	<b>Test Date:</b> 17/10/12
<b>Order No.:</b> ANNA	<b>Description:</b> ICE LINE
<b>Invoice No.:</b>	<b>Test Method:</b> Break
<b>Size:</b> 8 mm	<b>Peak Load:</b> 10 kN
<b>Length:</b> 0.4 m	<b>Test Duration:</b> 0.9 Minutes



TO CONVERT kN TO TONNES, MULTIPLY BY 0.102.  
OUR INSPECTION AND TESTING SERVICES DO NOT INCLUDE CRACK TESTING  
OR OTHER SPECIALISED SURFACE INSPECTION.

CALIBRATED BY AUSTRALIASIAN CALIBRATING SERVICES 14-12-10

Test Results
<input checked="" type="checkbox"/> Acceptable
<input type="checkbox"/> Not Acceptable

Conducted by:   
Adam Thompson

*Blew @ end of stitch.*