


Certificate of Testing

CHAIN & RIGGING SUPPLIES LTD
136 Captain Springs Rd, Onehunga
P O Box 13 312, Onehunga, Auckland, N.Z.
Ph: 09 636 4775 Fax: 09 636 7543
158 TONNE COMPUTERISED TESTING EQUIPMENT

Customer: TREE TOOLS	Test Number: 17593
Serial No.: 1	Test Date: 17/10/12
Order No.: ANNA	Description: OCEAN VECTRAN
Invoice No.:	Test Method: Break
Size: 6 mm	Peak Load: 16 kN
Length: 0.25 m	Test Duration: 0.5 Minutes



TO CONVERT kN TO TONNES, MULTIPLY BY 0.102.
OUR INSPECTION AND TESTING SERVICES DO NOT INCLUDE CRACK TESTING
OR OTHER SPECIALISED SURFACE INSPECTION.

CALIBRATED BY AUSTRALIASIAN CALIBRATING SERVICES 14-12-10

Test Results
<input checked="" type="checkbox"/> Acceptable
<input type="checkbox"/> Not Acceptable

Conducted by:

Adam Thompson

Blew @ end of stitch.